

The calibration process




Diagram to show the aperture and its radial segments in relation to the centre of rotation of the PCF




FIG 3